

Product data sheet

Specifications



Horizontal meter sockets, 2
ringless sockets, horn bypass, 4
jaws, OH, UG, 100 A

UHT2R1121B

⚠ Discontinued on: Sep 21, 2020

⚠ Discontinued

Product availability: Non-Stock - Not normally stocked in
distribution facility

Main

Product Type	Meter Socket
Rated Current	100 A
Number of Meter Sockets	2
Number of Phases	1 phase
Rated Operational Voltage	600 V AC

Complementary

Number of Jaws	4 without jaw release
Bypass Type	Horn bypass
Meter Socket Type	Ringless
Certifications	UL Listed
Enclosure Rating	NEMA 3R
Box Number	13R
Wire Gauge	AWG 6...250 kcmil (aluminium/copper) main lugs AWG 8...AWG 2/0 (aluminium/copper) branch lugs
Service Feed Location	UG OH
Wiring Configuration	3-wire
Hub Type	A ACP closing plate

Ordering and shipping details

Category	US10DE400039
Discount Schedule	0DE4
GTIN	00785901218081
Returnability	No

Packing Units

Unit Type of Package 1	PCE
Nbr. of units in pkg.	1
Package 1 Height	25.0 in (63.5 cm)
Package 1 Width	15.0 in (38.1 cm)

Price is "List Price" and may be subject to a trade discount – check with your local distributor or retailer for actual price.

Disclaimer: This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications

Package 1 Length	6.00 in (15.24 cm)
Package weight(Lbs)	27.00004 lb(US) (12.247 kg)

Contractual warranty

Warranty (in months)	18
----------------------	----



Environmental Data

Schneider Electric aims to achieve Net Zero status by 2050 through supply chain partnerships, lower impact materials, and circularity via our ongoing “Use Better, Use Longer, Use Again” campaign to extend product lifetimes and recyclability.

[Environmental Data explained](#) >

[How we assess product sustainability](#) >

Use Better

Materials and Substances	
EU RoHS Directive	Under investigation
California proposition 65	WARNING: This product can expose you to chemicals including: Nickel (Metallic), which is known to the State of California to cause cancer, and Toluene, which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

Use Longer

Lifetime extension	
Repair	No